

	BY-001 REPLACE: HONDA 30510-PT2-006,30510-P73-A01, 30510-P73-A02, ROVER GCL195, NEC100530 BOSCH F000 ZS0 116 UF-89
	BY-006 REPLACE: HONDA 30500-P0H-A01,30500-PAA-A01,30500-PCA-003, HITACHI CM1T-228 ROVER NEC100750,GCL207 UF-203
	BY-041 REPLACE: HONDA 30520-PGK-A01, 30520-PVF-A01, 30520-P8E-A01 30520-P8F-A01, 30520-P8F0A02, 30520-PVJ-A01 30520-P8E-A00, 30520-RCA-A02 UF-400
	BY-062 REPLACE: HONDA 30520-PNA-007, 30520-RRA-007, 30520-PCX-007 UF-311
	BY-068 REPLACE: HONDA 30521-PWA-003, CM11-108 UF-374
	BY-069 REPLACE: HONDA 30520-PWC-003, CM11-110 UF-581
	BY-070 REPLACE: HONDA 30520-PWA-003, CM11-109 UF-373
	BY-082 REPLACE: HONDA 30520-RNA-A01 UF-582

	BY-088 REPLACE: HONDA 30520-P8E-A01 UF-242
	BY-089 REPLACE: HONDA 30520-R40-007 UF-602
	BY-090 REPLACE: HONDA 30520-RN0-A01 UF-624
	BY-190 REPLACE: HONDA 30520-RB0-003 HITACHI CM1T-116 UF-581
	BY-252 REPLACE: HONDA 30520-R1A-A01,C1823 UF-672
	BY-266 REPLACE: HONDA 30510-PV1-A01 UF-108
	BY-272 REPLACE: HONDA 30520-PT9-A02 UF-205

	BY-299 REPLACE: ACURA 30520-PNC-004 UF-417
	BY-320 REPLACE: HONDA 30520-5A2-A01 UF-712
	BY-321 REPLACE: HONDA 30520-5G0-A01 UF-713
	BY-322 REPLACE: HONDA 30520-R70-A01,30520-R70-S01 SMP#UF603
	BY-331 REPLACE: HONDA 30521-RBJ-S01,30521RBJ013 SMP#UF676
	BY-332 REPLACE: HONDA 30520RBJS01,CM11-119,30520RBJ013 SMP#UF675
	BY-336 REPLACE: HONDA 30520-5R0-013,305205R0003 SMP#UF749
	BY-339 REPLACE: HONDA 30520-59B-013 SMP#UF781