





	BY-028 REPLACE: JAGUAR C2S11480,C2S42673,C2S7928 SPARKREN BY-028 UF-435
	BY-065 REPLACE: LAND ROVER 4744015,4526466 JAGUAR AJ8-10445,AJ83415,AJ87644 SPARKREN BY-065 UF-519
	BY-143 REPLACE: LAND ROVER ERR6045,ERR6566 ALFA ROMEO 60558152,60586072,60809606 FIAT 60558152,60809606,7648797,76487907 BOSCH 0221503407 UF-545
	BY-157 REPLACE: REPLACE: NEC101000 BMW/LAND ROVER 12131748018,1748018,1748017 BOSCH 0221504004, 0221501004 UF-300
	BY-179 REPLACE: FORD 2W4Z-12029-EA,2W4Z-12A366-BB JAGUAR XR827823 FD-506
	BY-180 REPLACE: FORD 2W4Z-12029-AB,1W4Z-12029-AA FORD 2W4E-12A366-AC/AD JAGUAR AJ86929,XR842741,C2S42751 FD-496
	BY-192 REPLACE: JAGUAR LNE1510AB,XW93-12029-AB MERC MB97700-0280 UF-415 Note: 4 PINS

	BY- 193 REPLACE: JAGUAR LHE1510AA,LHE1510AB UF-384 Note: 2 PINS
	BY-194 REPLACE: JAGUAR LCA 1510 AB UF-347
	BY-195 REPLACE: NEC90013A NEC000120 NEC100730(L) BERU 0040100402 NOTE: BLACK BOOT
	BY-196 REPLACE: ROVER NEC000130,NEC100870 BERU 0040100502 NOTE: RED BOOT
	BY-198 REPLACE: LAND ROVER NEC000110L,NEC000070L ROVER NEC000070,NEC000110 UF-534
	BY-199 REPLACE: LAND ROVER NEC100730L, NEC000120L DENSO MB029700-8230 BERU ZS509,ZS501 BERU 40100509,40100501,0040100509,0040100501 ROVER NEC100730,NEC000120
	BY-341 REPLACE: Rover ERR6566 SMP#UF545