

	<p>BY-018</p> <p>REPLACE: SUBARU 22433-AA41A,22433-AA570,22433-AA410 22433-AA41B UF-324</p> <p>NOTE: 4 PINS</p>
	<p>BY-075</p> <p>REPLACE: SUBARU 22433-AA540,22433-AA418,22433-AA480 UF-504</p>
	<p>BY-087</p> <p>REPLACE: SUBARU 22433-AA550,22433-AA551,22433-AA451 UF-528</p>
	<p>BY-154</p> <p>REPLACE: SUBARU 22433-AA600, 22433-AA601, 22433-AA602 UF-665</p>
	<p>BY-215</p> <p>REPLACE: SUBARU 22433-AA240,22433-AA370 UF-159</p>
	<p>BY-216</p> <p>REPLACE: SUBARU 22433-AA230,22433-AA360 UF-160</p>
	<p>BY-217</p> <p>REPLACE: SUBARU 22433-AA400 UF-193</p> <p>NOTE: 3 PINS</p>

	BY-218 REPLACE: SUBARU 22433-AA580,22433-AA50A 22433-AA500 UF-538 NOTE: 4 PINS
	BY-249 REPLACE: SUBARU 22433-AA441, 22433-AA530 UF-287 NOTE: RED BOOT
	BY-273 REPLACE: SUBARU 22433-AA610 UF-682
	BY-280 REPLACE: SUBARU 22433-AA560,22433-AA421,22433-AA561 UF-480
	BY-287 REPLACE: SUBARU 22433-AA590 UF-625
	BY-288 REPLACE: SUBARU 22433-AA612 UF-666
	BY-305M REPLACE: SUBARU 22433-AA620,22433-A621,22433-AA62A UF-668

	<p style="text-align: center;">BY-315</p> <p>REPLACE: SUBARU 22433-AA630 SMP#UF664</p>
	<p style="text-align: center;">BY-316</p> <p>REPLACE: SUBARU 22433-AA650 SMP#UF710</p>
	<p style="text-align: center;">BY-317</p> <p>REPLACE: SUBARU 22433-AA680,22433-AA681,22433-AA67B SMP#UF720</p>
	<p style="text-align: center;">BY-342</p> <p>REPLACE: Subaru 22433-AA700 SMP#UF747</p>