





| | |
|---|--|
|  | BY-021 REPLACE: SUZUKI 33410-77E11 UF-169 |
|  | BY-023 REPLACE: SUZUKI 33400-65G00, 33400-65G01 9C19-0370 UF-280 |
|  | BY-031 REPLACE: SUZUKI 33410-77E21, 33410-77E22 UF-237 |
|  | BY-061 REPLACE: SUZUKI 33410-66D10 CHEVROLET 30020581 UF-268 |
|  | BY-067 REPLACE: NISSAN 22448-EA000,22448-JA00C,22448-ED000,22448-JA00A UF-549 |
|  | BY-086 REPLACE: SUZUKI 33400-65J00 UF-562 |
|  | BY-091 REPLACE: SUZUKI 33400-62J00,33410-66D01,33410-66D00 UF-268 |

| | |
|---|--|
|  | <p style="text-align: center;">BY-139</p> <p>REPLACE: GM 96253555, 93363483 DELPHI 19005236, 19005265 ISUZU 8-01104-039-0 SUZUKI 33410-84Z00 UF-503 Note: 3 Pins</p> |
|  | <p style="text-align: center;">BY-237</p> <p>REPLACE: GM 96414260,25181813 DELPHI 19005277 SUZUKI 33410-86Z10 UF-561</p> |
|  | <p style="text-align: center;">BY-253</p> <p>REPLACE: SUZUKI 33410-86Z00 UF-552</p> |
|  | <p style="text-align: center;">BY-269</p> <p>REPLACE: GM 12618542,12590990 UF-569</p> |
|  | <p style="text-align: center;">BY-285</p> <p>REPLACE: SUZUKI 22433-51K20 UF-634</p> |