













	BY-008 REPLACE: GM D539,D540,D546,D555,D576,1103608,1103646,1103662,1103663, 1103744,1103745,1103746,10468391,10472401,10495121,10497771 ISUZU 8-140468-391-0,8-10472-401-0 DR39T
	BY-094 REPLACE: GM 12558693 H6T551712C UF-271
	BY-138 REPLACE: GM 10450424, 10490192, 1104038 DAEWOO 88921374, 96350585, E586A ISUZU 8-01104-038-0 OPEL 1208051 UF-356 Note: 4 Pins
	BY-139 REPLACE: GM 96253555, 93363483 DELPHI 19005236, 19005265 ISUZU 8-01104-039-0 SUZUKI 33410-84Z00 UF-503 Note: 3 Pins
	BY-140 REPLACE: GM 12556450, 12558948 UF-192
	BY-185 REPLACE: GM 12568062 UF-303
	BY-187 REPLACE: GM 12573190 UF-414

	BY-188 REPLACE: GM 10457730, 19005218 UF-262
	BY-189 REPLACE: GM 12583514 BOSCH 0221604104 UF-375
	BY-220 REPLACE: GM D524, D531, D536, 1876209, 1985474, 1988908 DR-32
	BY-221 REPLACE: GM D530, D523, D532, 8131936, J8131936, 1875894, 1985473, 10497132, 1694925-C1 DR-31
	BY-223 REPLACE: GM D525, D527, D528, D529, 1187847, 8134003, DGG-322, DGG-421 J8134003, 1115444, 1115445, 1115447, 1115448, 1115455, DGG-222 DR-35
	BY-224 REPLACE: GM 10489421 ISUZU 8104894210 DR-49
	BY-237 REPLACE: GM 96414260, 25181813 DELPHI 19005277 SUZUKI 33410-86Z10 UF-561
	BY-238 REPLACE: GM 96453420 DAEWOO 96453420 UF-698

	BY-239 REPLACE: GM 12595088,H6T40171ZC GM 12568185,12587153 ACDELCO D508A & D516A UF-434
	BY-248 REPLACE: GM 12596547,12612369,12619472,12496547,8125965470 UF-497
	BY-250 REPLACE: GM 1104076 UF-266
	BY-251 REPLACE: GM 1104075 UF-265
	BY-255 REPLACE: GM 12594176 UF-564
	BY-265 REPLACE: GM 90584337,9117815/9118115 UF-279
	BY-267 REPLACE: GM 55570160,96476979 UF-220

	BY-268 REPLACE: GM 12578224,12589623 UF-491
	BY-269 REPLACE: GM 12618542,12590990 UF-569
	BY-270 REPLACE: GM9118114,90584336 UF-278
	BY-274 REPLACE: GM 12567285,12585765,89017778 UF-372
	BY-295 REPLACE: GM 12787707 UF-526
	BY-295G REPLACE: GM 12584368 UF-492
	BY-300 REPLACE: GM 12597745 UF-736

	<p>BY-306</p> <p>REPLACE: GM 96983945 UF-725</p>
	<p>BY-325</p> <p>REPLACE: GM 2587426 UF-391</p>