

	<b>BY-011</b> <b>REPLACE:</b> MAZDA CM5Z12029F UF-740
	<b>BY-013</b> <b>REPLACE:</b> Mazda BP4W-18-10XA EP19-18-18X HANSHIN DSC-550 MAZDA BPE8-18-10XC,BPE8-18-10XC-9U UF-383
	<b>BY-029</b> <b>REPLACE:</b> Mazda FP39-18-10XC  FORD FPY2-10-10X,FY2-180-10XC UF-235
	<b>BY-037</b> <b>REPLACE:</b> MAZDA ZZY1-18-100, ZL01-18-100A, ZL01-18-100B
	<b>BY-038</b> <b>REPLACE:</b> MAZDA FFY1-18-100 FORD FP85-18-100, FP85-18-100C UF-407
	<b>BY-052</b> <b>REPLACE:</b> MAZDA ZM01-18-100 UF-276
	<b>BY-054</b> <b>REPLACE:</b> FORD 2M2E-12366-AC,2M2Z-12029AC,AJ51-18-100 AJ51-18-100A UF-406 NOTE:GREY BOOT
	<b>BY-099</b> <b>REPLACE:</b> MAZDA N3H1-18-100,N3H1-18-100B N3H1-18-100A,N3H1-18-1009U,N3HI-18-100A9U UF-501

	<p align="center"><b>BY-109</b></p> <p><b>REPLACE:</b> FORD 988F-12029AB, 1S7G-12029AB 1067601, 1075786, 1130402, 1317972 MAZDA YF09-18-10X FD-497</p>
	<p align="center"><b>BY-111</b></p> <p><b>REPLACE:</b> MAZDA ZZM0-18-100, FSD7-18-100 FORD 88F-12029-A1A, 928F-12029-CA E8TF-12029-AA, E8TZ-12029-A, E9TF-12029-AA F1VU-12029-A, F5LU-12029-AA FD-487</p>
	<p align="center"><b>BY-181</b></p> <p><b>REPLACE:</b> MAZDA ZJ20-18-100A, ZJ20-18-100 UF-655</p>
	<p align="center"><b>BY-184</b></p> <p><b>REPLACE:</b> MAZDA 1F20-18-100, LF01-18-100 FORD 1S7G-12029-AC FD-501</p>
	<p align="center"><b>BY-189</b></p> <p><b>REPLACE:</b> FORD 1L8Z-12029-AB, MAZDA AJ03-18-100, AJ09-18-100 FD502 NOTE: BLACK BOOT</p>
	<p align="center"><b>BY-222</b></p> <p><b>REPLACE:</b> MAZDA PE01-18-100A, PE01-18-100 PE20-18-100, PE20-18-100A MAZDA H6T61271, H6T61171 UF-656</p>
	<p align="center"><b>BY-242</b></p> <p><b>REPLACE:</b> Mazda L3G2-18-100B-9U, L3G2-18-100A, L3G2-18-100A-9U. UF-540</p>